



# Upgrading from POWER5 to POWER6 @ Australia Post

2009 IBM Power Systems Technical Symposium. 10-13th August, Sydney, Australia

# Who is this bloke!?

- ❑ Chris Gibson - [chris.gibson@auspost.com.au](mailto:chris.gibson@auspost.com.au)
- ❑ AIX Specialist @ Australia Post.
- ❑ IBM CATE, System p platform and AIX 5L, technical writer for IBM Systems Magazine, IBM developerWorks and a co-author of the IBM Redbooks publication, "NIM from A to Z in AIX 5L."

## Purpose

- ❑ Share our POWER6 upgrade experience with AIX community.
- ❑ Exchange ideas with other AIX customers.
- ❑ Provide feedback to IBM development.

## Audience

- ❑ Technical
- ❑ AIX





# Introduction

- ❑ Discuss **my experiences** when upgrading a POWER5 595 to a new POWER6 595.
- ❑ **Not** intended as an official "how-to" guide
- ❑ Discussion on how I performed the upgrade and what decisions and **considerations** I made during the **planning and execution** phases.
- ❑ I hope that this information will **help others** who need to perform similar tasks within their own organizations or those of their customers.
- ❑ **Each environment is different.** Most sites customize their AIX and POWER hardware configuration to meet their requirements.
- ❑ What I describe here **may not match** what you have in **your environment**.
- ❑ **Use your best judgment and only apply if it is appropriate for your site.**
- ❑ **Only you can make this call**, as you know more about how your AIX and POWER infrastructure is configured (and why) than anyone else!

# Posts POWER and AIX Landscape

- ❑ An important note: **All of my LPARs were virtualized**; i.e. micro-partitioned, virtual I/O (VIO) for all disk and network devices.
- ❑ All physical devices were owned by the Virtual I/O servers (VIOS).
- ❑ There is **always an exception!** One LPAR had FC adapters for Tape.

~80 LPARs



# Upgrade Overview

- ❑ I needed to upgrade my existing System p® 595 (9119-595) landscape to the new POWER6 595 (9119-FHA).
- ❑ **MES upgrade.** MES stands for Miscellaneous Equipment Specification. An MES upgrade includes any server hardware change, which can be an addition, improvement, removal, or any combination of these.
- ❑ An important feature of an MES upgrade is that the **systems serial number does not change.**



# Upgrade Overview – continued.

- ❑ Essentially, our upgrade from POWER5 to POWER6 involved moving the [existing I/O drawers](#) (including internal disks, FC, and Ethernet adapters) from the POWER5 frame to the POWER6 frame.
- ❑ Once completed, the POWER6 system would be powered up and the IBM CE (Customer Engineer) would then hand back the system to me.
- ❑ Attempt to bring up the LPARs on the new POWER6 server.
- ❑ This was the first time I had migrated to a newer POWER platform using the MES upgrade method, and I had [concerns](#).
- ❑ In the past I had migrated AIX systems to newer platforms with both the [old and new systems sitting side by side](#).
- ❑ For example, POWER4 to POWER5:
  - New 9119-595 sat next to the old p4 p690.
  - Connected 595 to SAN and network.
  - Started moving LPARs from the p690 (one at a time) by [restoring a mksysb](#) using Network Installation Manager ([NIM](#)).

# Upgrade Overview – continued.

- The advantage with this method was if we had an issue on the new 595, we could **easily fallback** to the p690, as the original LPAR was still available. It also allowed us time to test the 595 before we unleashed any workload onto the system.
  - This gave us **greater confidence** that all our components were compatible (such as software and firmware) and functioning as expected. It essentially gave us time to **shake out any bugs** or issues with the new hardware.
- 
- ❑ This method was what I considered, at the time, my preferred way of performing the migration to POWER6.
  - ❑ MES upgrade method. Old p5 system shut down, rolled out the door, and the new p6 moved into its place.
  - ❑ IBM CE transfer I/O drawers, configure the system, verify it was OK, hand it back to me, and walk away (so to speak!).
  - ❑ The **'big bang'** upgrade approach. Not able to rehearse or test the upgrade process. *Potential* to be caught out by unknown issues.

# Upgrade Overview – continued.

- ❑ Concern if there was a problem with the 9119-FHA, we **did not have a way to easily back out** to the old system.
- ❑ Could not simply power up the old p5 and start the LPARs.
- ❑ **Nor could we test** that the new hardware was functioning OK, **in advance**, before activating the LPARs and running production workload.
- ❑ Given that this was an MES upgrade and that wasn't going to change, I set about **planning for the upgrade**.



# Planning and Preparation.

- Decide **migration approach**.
- Two choices here;
  - **Rebuild** VIOS and LPARs from mksysb. ☹
  - Attempt to **boot** them from disk. :-\
- Official** method to migrate LPARs to newer or different hardware was using a "mksysb clone" operation. Taking a mksysb of the LPAR and restoring it on the new p6 system.
- Interested in simply booting the LPARs on the new p6 595.
- Not guaranteed** to work. Need appropriate **device driver** filesets to support the new platform.
- Systems installed with "*Enable System Backups to install any system*" set to *Yes*.
- Enables systems to be installed on any other system (using cloning) by installing **all devices and kernels**. No guarantee is implied by this setting.
- Think about how Live Partition Mobility works**, and the fact that you can move a Virtual I/O client (VIOC) LPAR from one physical system to another (without a mksysb restore), I wonder if this may change in the future?
- /usr/lpp/bosinst/bosinst.template.README file for more details.

# Planning and Preparation - continued.

- ❑ Some evidence on the [AIX forums](#) suggested that this method may work. One customer had reported using this method when they upgraded from a p5 570 to a p6 570.
- ❑ MES upgrade [impact on I/O bus numbering and LPAR profiles?](#)
- ❑ 9119-595 to 9119-FHA MES upgrade instructions stated that the I/O bus numbering did not change after the upgrade.
- ❑ Were my LPAR profiles going to be recovered, and intact, on the new p6, or [would I need to rebuild?](#)
- ❑ The MES upgrade instructions stated the IBM CE should perform a Recover Partition Data operation, using the HMC, after the upgrade.
- ❑ I should not need to recreate all of my LPAR profiles from scratch (either using the System Planning Tool (SPT) or a scripting method).
- ❑ [System serial number was guaranteed not to change.](#) No application licensing problems.

# Planning and Preparation - continued.

- ❑ **My approach** to the upgrade. Boot LPARs (VIOS included) and use mksysb restore only if I had serious issues bringing up the systems (in a clean state).
- ❑ My procedure would be:
  - **Document virtual mappings** on each VIOS i.e. *lsmmap -all* and *lsmmap -all -net*.
  - Collect **PVID/LUNID** info for all VTDs backed by physical disks.
  - Take a mksysb of all LPARs and VIOS. Use these to restore from, if required.
  - Back up the managed systems **partition profile** data.
  - IBM CE perform the hardware upgrade to POWER6.
  - IBM CE restore the managed systems profile data from the previous backup.
  - **Verify profile** data for each AIX LPAR and VIOS is correct on the HMC.
  - Upon successful verification of LPAR and VIOS profiles, **boot each VIOS**.
  - Enter the SMS menu, confirm the boot list, and boot the VIOS.
  - **Verify the virtual device configuration** and status on each VIOS.
  - Perform a health check on each **VIOS**. If **health check** not successful → mksysb restore via NIM.
  - Upon successful verification of each VIOS, **boot each LPAR**.
  - Enter the SMS menu, confirm the boot list, and boot the LPAR.
  - If booting LPAR failed, restore LPAR from mksysb.
  - Correct the boot list on each LPAR.
  - Start functional verification of environment i.e. VIOS failover and **application startup and test**.
- ❑ Ensure the process executed with great deal of care and attention.
- ❑ Any unforeseen issues that could not resolve quickly → **revert to mksysb**.

# Planning and Preparation – FLRT - cont.

- ❑ Check software and hardware levels to support the new POWER6 platform.
- ❑ Used the IBM Fix Level Recommendation Tool (FLRT) to determine levels compatible with the 9119-FHA.
- ❑ FLRT provides recommended fix level information on key components of IBM POWER systems.
- ❑ Highly recommend tool when planning any type of AIX or POWER upgrade activity.

IBM - Fix Level Recommendation Tool - Windows Internet Explorer

Address: http://www14.software.ibm.com/webapp/set2/flrt/report?exp=y&expOs=&entm=9119-FHA&ghz=5.0&firmware=EH340\_039&aix=5300-07-05-0631&hacmp=5.4&hmc=7.3.4&vios=1.5.2.1&reportname=&submit=Submit

**For administrators of IBM Power Systems**

The following consolidated information is for guidance purposes only. This information was obtained from generally available product support documentation. These combinations of product levels are supported by IBM.

**Date:** 2008.12.10  
**Model:** IBM Power 595 (9119-FHA) (9119-FHA)  
**Speed:** 5.0 ghz.

Product	Version/Release	Status
AIX	5300-07-05-0631	✓
PowerHA	5.4	✓
HMC	7.3.4	⚠
Firmware	EH340_039	✓
Virtual I/O Server	1.5.2.1	⚠

**Detailed results**

Product	Detail information	
⚠ HMC	Update recommended: HMC PTF MH01148 Mandatory fix for HMC 7.3.4.0	<a href="#">Get the update</a>
⚠ Virtual I/O Server	Update recommended: IZ22147 Fix for IVM's, usage of the 'tssp' command on a VIOS system. For VIOS 1.5.2.1-PP-11.1 only. Do not apply to any other VIOS level.	<a href="#">Get the update</a>
⚠ Virtual I/O Server	Update recommended: IZ21343 Required for a problem that occurs when SEA is configured to use TCP segmentation offload (tso). For VIOS 1.5.2.1-PP-11.1 only. Do not apply to any other VIOS level.	<a href="#">Get the update</a>
⚠ Virtual I/O Server	Update recommended: IZ26655 Fix for the Subsystem Device Driver Patch Control Module (SDPCM). For VIOS 1.5.2.1-PP-11.1 only. Do not apply to any other VIOS level.	<a href="#">Get the update</a>
⚠ Virtual I/O Server	Update recommended: IZ22151 Fix for HEAs for high defunct process count and memory leak impact. For VIOS 1.5.2.1-PP-11.1 only. Do not apply to any other VIOS level.	<a href="#">Get the update</a>

# Planning and Preparation – Levels - cont.

- ❑ In the [months leading up to the upgrade](#), we updated the following components to the following levels, in the following order:
  - HMC V7R3.4.0 + MH01152
  - Firmware Updated various H/W (for example, FC, SCSI and Ethernet adapters)
  - VIOS 1.5.2.1-FP-11.1 + SDDPCM 2.2.0.4
  - AIX 5300-07-05-0831
  - HACMP 5.4.1.3 + RSCT fixes
  
- ❑ Prior to upgrade, [captured](#) a plethora of [configuration information](#) relating to the 595, AIX, VIOS, HACMP, and HMC.
  
- ❑ If I needed to recover anything from scratch, I wanted to be well prepared and have a wealth of information at hand should I need it.
  
- ❑ The following highlights just some of the data I collected using scripts and other methods:
  - Ran my *AIXinfo* script to collect vast amounts of information relating to the AIX configuration of each and every LPAR.
  
  - The script ran several system commands, such as [oslevel](#), [lppchk](#), [instfix](#), [lsconf](#), [lscfg](#), [lsdev](#), [lsattr](#) and [many more](#). The information was stored in a text file on another system.
  
  - Created a [Microcode Discovery Service](#) (MDS) Report for each VIOS and any LPAR that contained physical hardware like FC adapters or SCSI disks.

# Planning and Preparation – Levels - cont.

**Microcode Discovery Service**

Report

This report contains all the microcode packages found by Microcode Discovery Service on the system you specified.

The report indicates if installed packages are at the latest level. If the installed package is downlevel from what is available the suggested action will be "Update". In some cases it may not be possible to determine the installed level or detect if the installed level is the latest; in this scenario the suggested actions will be "Inspect" or "Research" respectively.

Before installing any microcode, be sure to review its README file.

### Microcode by Host

**Ixio5**

IP Addr: 10.3.29.14

Model: 9119-595 Serial: 8379A80

Partition Type: service partition of 9119-595/8379A80

Data taken at: 2009.01.20 12:02:00 Microcode catalog: 2009.01.19

Devices found on Ixio5:

Device	Logical Device	Suggested Action	Installed Level	Latest Available
9110-510				
9110-51A				
9111-285				
9111-520				
9113-550				
9115-505				
9118-561				
9117-570				
9118-575				
9119-590				
9119-595	system	Update	SF240_338	SF240_358
9131-52A				
9133-55A				
9124-xxx				
9123-xxx				
9405-520				
9406-520				
9406-550				
9406-570				
9406-595				
9407-515				
9406-525				

# Planning and Preparation – Levels - cont.

## ❑ Information from the HMC:

- LPAR profile (CPU/Memory allocation).
- Managed system properties.
- Physical I/O adapter assignment.
- Virtual adapter definitions.
- This could be captured using the SPT or simple screen captures from the HMC.

## ❑ Virtual I/O mapping and configuration

- `lsmmap -all` and `lsmmap -all -net` output.
- Shared Ethernet Adapter (SEA) settings.
- VTD mapping.
- `pcmpath` output.
- `vhost` slot numbers, and more.
- [Location codes for the VIOS rootvg disks](#), which proved to be an important step.

# Planning and Preparation – Levels - cont.

- ❑ Cable locations and labels.
  - All SAN and network connections would be unplugged during the migration. Connected again after upgrade. **Label each cable** so they are connected to the right location after the upgrade.
- ❑ Build documentation.
  - On hand in case I needed to refer to it. Outlined how systems had been built and configured originally.
- ❑ HACMP information.
  - Several HACMP cluster nodes. Cluster information i.e. clstat, cltopinfo, **clsnapshot**, cldump, clRGinfo, and cldisp. Exported cluster configuration using the HACMP Online Planning Worksheets, such as # smit cl\_export\_def\_olpw.dialog.
- ❑ HACMP configuration for each **cluster synchronized** prior to the upgrade.
- ❑ Reviewed AIX and VIOS error report. Catching (and **resolving**) issues before a major upgrade can save you from headaches later on.
- ❑ Check the HMC for any open hardware events, like \$ lssvcevents -t hardware.
- ❑ **HMC readiness checker** to identify any 595 hardware issues that may impact the upgrade. You'll find this task on the HMC under "Updates." Once you select a managed system, you can click on Check system readiness.



# POWER6 Upgrade.

- ❑ On the day of the upgrade, I shut down all the LPARs and handed the system over to the IBM CE.
- ❑ 6 hours performing hardware upgrade.
- ❑ HACMP clustered systems. Production workload was processed on another 595 while one was down for the upgrade.
- ❑ When the CE gave the system back to me, the first thing I did was check that all of my cables were plugged in correctly. They were.
- ❑ Next I verified that all my LPAR profiles had been recovered successfully on the new system. They had.
- ❑ I double checked each profile and found that the partition id and the bus numbers had not changed.
- ❑ Also, the location codes for all adapters (e.g. TY-P1-C02) had not changed.
- ❑ The serial number, as promised, had not changed.
- ❑ This was all good news!

# POWER6 Upgrade - continued.

Hardware Management Console

Systems Management > Servers >

Select	Name	ID	Status	Processing Units	Memory (GB)	Active Profile	Environment
<input type="checkbox"/>	bvio1	2	Running		0.5	2 default	Virtual I/O Server
<input type="checkbox"/>	bvio2	3	Running		0.5	2 default	Virtual I/O Server
<input type="checkbox"/>	bxaib01adm	4	Running		2	100 default	AIX or Linux
<input type="checkbox"/>	bxaib02adm	5	Running		2	13 default	AIX or Linux
<input type="checkbox"/>	bxaib03	6	Running		0.5	2 default	AIX or Linux
<input type="checkbox"/>	bxaib04adm	7	Running		0.1	1 default	AIX or Linux
<input type="checkbox"/>	bxaib05adm	10	Running		0.1	1 default	AIX or Linux
<input type="checkbox"/>	bxaib06adm	8	Running		0.2	8 templememory	AIX or Linux
<input type="checkbox"/>	bxaib07adm	9	Running		1	1 default	AIX or Linux
<input type="checkbox"/>	bxxim1	1	Running		0.2	1 default	AIX or Linux

General Processors Memory **I/O** Migration Power-On Parameters Capabilities Advanced

Detailed below are the physical I/O resources for the managed system. Select slot to view the properties of e

Unit	Bus	Slot	Description	I/O Pool Id
U5791.001.9980XTY-P1	10	T6	SCSI bus controller	Unassigned
U5791.001.9980XTY-P1	10	C08	4 Gb Dual-Port Fibre Channel PCI-X 2.0 DDR Adapter	Unassigned
U5791.001.9980XTY-P1	10	C09	Ethernet controller	Unassigned
U5791.001.9980XTY-P1	10	C10	SCSI bus controller	Unassigned
U5791.001.9980XTY-P1	11	C01	Ethernet controller	Unassigned
U5791.001.9980XTY-P1	11	C02	Ethernet controller	Unassigned
U5791.001.9980XTY-P1	11	C03	4 Gb Dual-Port Fibre Channel PCI-X 2.0 DDR Adapter	Unassigned
U5791.001.9980XTY-P1	11	C04	RAID Controller	Unassigned
U5791.001.9980XTY-P1	12	T5	SCSI bus controller	Unassigned
U5791.001.9980XTY-P1	12	C05	4 Gb Dual-Port Fibre Channel PCI-X 2.0 DDR Adapter	Unassigned
U5791.001.9980XTY-P1	12	C06	Ethernet controller	Unassigned
U5791.001.9980XTY-P1	12	C07	4 Gb Dual-Port Fibre Channel PCI-X 2.0 DDR Adapter	Unassigned
U5791.001.9980XTY-P2	13	T6	SCSI bus controller	Unassigned
U5791.001.9980XTY-P2	13	C08	4 Gb Dual-Port Fibre Channel PCI-X 2.0 DDR Adapter	Unassigned
U5791.001.9980XTY-P2	13	C09	Ethernet controller	Unassigned

Total: 72 Filtered: 72

# Booting each VIOS.

- ❑ Next step was to **boot the VIOS**.
- ❑ Activated one VIOS.
- ❑ Took a while. Large number of disks disks (100+) assigned to VIOS. 4 paths to SAN. **All scanned**.
- ❑ Entered SMS. Confirmed **boot list** contained **correct rootvg disk for this VIOS** (which is where my documentation came in very handy).
- ❑ Needed to be careful here. Several disks identified with an AIX image installed. Did *not* belong to this VIOS rootvg!
- ❑ rootvg disks that belonged to client LPARs. **Pick wrong disk, boot wrong system!**
- ❑ **Important to collect the location codes** for VIOS rootvg disks prior to the upgrade.
- ❑ Exited SMS. VIOS boot as normal. The system came up without any errors.
- ❑ Console login (padmin). Ran `lsmap -all` and `lsmap -all -net`. All virtual adapter mappings and SEAs were available.
- ❑ Only difference observed, vhost location codes changed, from 595 to FHA (as shown below); however, slot numbers and serial number identical:

```
< vhost0 U9119.595.8369B40-V2-C20 0x00000000
---
➤ vhost0 U9119.FHA.8369B40-V2-C20 0x00000000
```
- ❑ Boot list on VIOS changed. **hdisk0 and ent0** in list. Change boot list:

```
# bootlist -m normal hdisk0 hdisk8
```
- ❑ Expected. **NVRAM** (contains the boot list) **not carried over** from the old p5 to the new p6.

# VIOS health checks.

- ❑ Before starting LPARs. Performed health checks on [VIOS. General health](#). Looking anomalies, such as devices in *Defined* state, permanent hardware errors in error log, etc.

VIOS checks	Description
<code>lsconf</code>	Ensure processor shows POWER6
<code>ioslevel</code>	Confirm VIOS level
<code>cfgdev</code>	Check for any missing device filesets
<code>lsmmap -all</code>	Check VTD mapping
<code>lsmmap -all -net</code>	Check SEA configuration
<code>lsdev -virtual</code>	Check Virtual devices are <i>Available</i>
<code>lsdev -type disk</code>	Check disk devices are <i>Available</i>
<code>lsdev -type adapter</code>	Check adapters are <i>Available</i>
<code>entstat -all</code>	Check SEA status and priority
<code>errlog</code>	Review errlog for any critical errors
<code>lsdev -dev fscsiX -attr</code>	Review device attributes
<code>lsdev -dev hdiskX -attr</code>	Review disk device attributes
<code>lspv</code>	Check disk pvids
<code>pcmpath query adapter</code>	Check SDDPCM adapter status
<code>pcmpath query device</code>	Check SDDPCM disk device status and

# VIOS health checks – continued.

<code>pcmpath query adapter</code>	Check SDDPCM adapter status
<code>pcmpath query device</code>	Check SDDPCM disk device status and LUNIDs
<code>pcmpath query wwpn</code>	Check FC adapter WWPNS known to SDDPCM
<code>pcmpath query version</code>	Check SDDPCM level
<code>lspath</code>	Check all disk paths are enabled
<code>netstat -nr</code>	Check default gateway

# Booting the LPARs.

- ❑ Once both VIOS activated OK. [Start AIX LPAR](#). Boot into SMS. Review boot list. Verified correct rootvg disk in list. It was. The LPAR booted as normal.

## AIX Health Checks.

- ❑ Health checks on AIX LPAR. Verified operating as expected. Reset boot list:

```
# bootlist -m normal hdisk0 blv=bos_hd5 hdisk1 blv=bos_hd5
```

- ❑ [Pay particular attention if you use multibos](#) on your AIX systems. May have [two BLVs](#). Choose correct [disk partition](#) to boot from (e.g. part=2 or part=4); otherwise, could boot from older image. Recommend you [remove multibos instances](#) (multibos -R) prior to upgrade; [avoid confusion](#).

```
PowerPC Firmware
```

```
Version EH340_039
```

```
SMS 1.7 (c) Copyright IBM Corp. 2000,2008 All rights reserved.
```

```
-----  
Select Device
```

```
Device Current Device
```

```
Number Position Name
```

```
1. - SCSI 136 GB Harddisk, part=2 (AIX 5.3.0)
```

```
( loc=U9119.FHA.8369B40-V22-C46-T1-L8100000000000000 )
```

```
2. - SCSI 136 GB Harddisk, part=4 (AIX 5.3.0)
```

```
( loc=U9119.FHA.8369B40-V22-C46-T1-L8100000000000000 )
```

# AIX Health Checks – cont.

AIX Checks	Description
lsconf	Ensure processor shows POWER6
cfgmgr	Check for any missing device filesets
<pre>lsdev -C   grep Defined lsdev -Cc adapter lsdev -Cc disk</pre>	Check devices are in the correct state
lparstat -i	Verify LPAR config
oslevel -s	Verify AIX SP level
oslevel -r	Verify AIX TL.
bootlist -m normal -o	<p>Check bootlist settings.</p> <p>Expect output similar to:</p> <ul style="list-style-type: none"><li>- For mirrored rootvg (including the VIOS): # bootlist -m normal -o hdisk0 blv=bos_hd5 hdisk4 blv=bos_hd5</li><li>- For SAN boot rootvg: # bootlist -m normal -o hdisk0 blv=bos_hd5 hdisk0 blv=bos_hd5</li></ul>

# AIX Health Checks – cont.

```
instfix -i |grep AIX
instfix -i |grep SP
instfix -icqk 53-07-050831_SP | grep ":-:"
instfix -icqk 5300-07_AIX_ML |grep ":-:"
```

Detects any missing AIX TL or SP filesets

```
lsvg -l rootvg |grep stale
```

Check for 'stale' partitions in rootvg

```
df
mount
lsvg | lsvg -il | grep close
```

Check all necessary file systems are mounted.

```
df /var
```

Check for full /var

```
df /tmp
```

Check for full /tmp

```
sysdumpdev -l
```

Check for proper system dump config

```
lsattr -El mem0
```

Ensure proper memory configuration

```
emgr -l
```

Check 'efix' inventory if any

```
lppchk -v -m3
```

Verify installed filesets

```
lppchk -c -m3
```

Sum check installed filesets



# AIX Health Checks – cont.

<code>lspcs -a</code>	Verify paging space
<code>smtctl</code>	Verify smt on/off all the nodes
<code>lssrc -ls xntpd   grep "Reference Id"</code>	Check ntp on the nodes
<code>vmo -a</code>	Check all vmo settings
<code>no -a</code>	Check all network options settings
<code>netstat -nr</code>	Check route table
<code>lspath</code>	Check all paths are enabled
<code>errpt</code>	Check for any permanent hardware errors or other critical errors
<code>tail -100 /var/log/syslog</code>	Check for any critical errors
<code>alog -of /var/adm/ras/conslog</code>	Review errors in the console log.
<code>cat /etc/qconfig lpstat</code>	Check print queues are defined and enabled.
<code>lssrc -a</code>	Review <i>active</i> and <i>inoperative</i> subsystems.
<code>pstat -a   grep aio lsattr -El aio0</code>	Verify AIO is configured.

# More Checks.

- ❑ Use the *lsconf* command. Quickly confirm the LPARs now running on POWER6.
- ❑ "System Model" changed, 9119-595 to **9119-FHA**, processor type and speed.

```
System Model: IBM,9119-595
Machine Serial Number: XXXXXXXX
Processor Type: PowerPC_POWER5
Number Of Processors: 4
Processor Clock Speed: 2302 MHz
CPU Type: 64-bit
Kernel Type: 64-bit
LPAR Info: 6 bxaix03
Memory Size: 2048 MB
Good Memory Size: 2048 MB
Platform Firmware level: SF240_338
Firmware Version: IBM,SF240_338
```

```
System Model: IBM,9119-FHA
Machine Serial Number: XXXXXXXX
Processor Type: PowerPC_POWER6
Number Of Processors: 4
Processor Clock Speed: 5000 MHz
CPU Type: 64-bit
Kernel Type: 64-bit
LPAR Info: 6 bxaix03
Memory Size: 2048 MB
Good Memory Size: 2048 MB
Platform Firmware level: EH340_039
Firmware Version: IBM,EH340_039
```

# VIOS failover verification.

- ❑ Satisfied each VIOS was in good shape.
- ❑ VIOC LPARs running fine.
- ❑ Performed VIOS failover tests.
- ❑ Ensure redundancy of dual VIOS had not been compromised as a result of the upgrade.
- ❑ Some of the tests included:
  - Shutdown one VIOS, ensure all client LPARs not impacted e.g. SEA failover, IP connectivity OK, loss of path (and/or mirror), disk traffic OK.
  - Restart VIOS, ensure fallback OK e.g. SEA fallback, IP connectivity OK, path recovery (and/or re-sync mirror), disk traffic OK.
  - Ensure any LPAR with mirrored rootvg (re)synced before and after each VIOS shutdown/restart.
  - Repeat the same verification procedures for the second VIOS.
  - Disconnect FC and network cable (one at a time) to ensure that disk and network I/O on VIOCs not impacted.

# Plan B

- If booting from disk had been unsuccessful, for whatever reason.
- Instigate Plan B.
- Involve **restoring** VIOS and LPARs **from a mksysb using NIM.**
- NIM master was located on a different 595 each time.
- Tested method on subsequent POWER6 upgrade. Worked equally well as just booting.
- Requires **more time.**
- No reconfiguration (apart from the boot list)
- Good idea to create a **new SPOT** on your NIM master **for each VIOS.**
- Create the **SPOT from a mksysb** of the VIOS (as shown below).

## Define a Resource

Type or select values in entry fields.  
Press Enter AFTER making all desired changes.

	[Entry Fields]	
* Resource Name	[hvio3-spot]	
* Resource Type	spot	
* Server of Resource	[master]	+
* Source of Install Images	[hvio3-mksysb]	+
* Location of Resource	[/export/nim/spot]	/
...		

# Plan B – cont.

- Change "Remain NIM client after install?" to **no** when configuring the VIOS NIM client
- BOS installation.
- Prevent IP address being configured on physical network adapter used for the install.
- If IP accidentally configured on this physical interface and it was part of a SEA.
- May fail to configure as the physical **device is already in use**.

```
Install the Base Operating System on Standalone Clients

Type or select values in entry fields.
Press Enter AFTER making all desired changes.

* Installation Target
* Installation TYPE
* SPOT
LPP_SOURCE
MKSYSB
BOSINST_DATA to use during installation
IMAGE_DATA to use during installation
RESOLV_CONF to use for network configuration
Customization SCRIPT to run after installation
Customization FB Script to run at first reboot
ACCEPT new license agreements?
Remain NIM client after install?
...

[Entry Fields]
hvio3
mksysb
hvio3-spot
[] +
hvio3-mksysb
[] +
[] +
[] +
[] +
[] +
[] +
[yes] +
[no] +
```

# Post Upgrade.

- ❑ Re-integrated HACMP nodes back into cluster
- ❑ Performed failover and fallback tests.
- ❑ No issues were discovered.
- ❑ A few post-upgrade tasks to perform:
  - Backing the up LPAR profile data, again!
  - Performing a backup of the HMC.
  - Taking a mksysb of each VIOS and all the AIX LPARs.
  - Reviewing any 'open' hardware events on the HMC.

# Summary.

- ❑ Initially concerned with the approach for this upgrade.
- ❑ Unscathed.
- ❑ Specific cases. MES upgrade and booting LPARs from disk.
- ❑ Certainly an option **worth considering**.
- ❑ Particularly **if LPARs are all VIO clients** & don't use any physical devices of any kind.
- ❑ There are no guarantees.
- ❑ Choose **carefully** and **test** thoroughly in your environment\*.
- ❑ mksysb clone is the supported way to migrate.
- ❑ Downside. mksysb restore will require more time.
- ❑ Down-time required for the restore may not be palatable in some cases i.e. **no HA**.
- ❑ Based on my experience, both methods achieved the same **satisfactory result**.

\*We were able to do some tests with lab equipment to *simulate* the upgrade.  
Not everyone has the resources to do this!

# References.

- ❑ Upgrading from POWER5 to POWER6.

[http://www.ibm.com/developerworks/aix/library/au-upgrade\\_power6](http://www.ibm.com/developerworks/aix/library/au-upgrade_power6)